



Polyguard 6612

COAL TAR EPOXY

Product Description: Polyguard 6612 is a robust two-component coal tar epoxy system that forms a tough, flexible coating without a primer. It offers exceptional corrosion resistance against seawater, petroleum, and harsh environments. It is ideal for heavy-duty applications and effectively protects steel and concrete in severely corrosive conditions.

Typical Uses: Polyguard 6612 is the ultimate solution for protecting steel pipelines carrying sewage and industrial water, as well as marine structures like offshore drilling rigs and dam gates, from severe corrosion. Its versatile application extends to petroleum and non-potable water storage tanks, ensuring long-lasting durability in challenging environments.

Perfectly suited for wastewater treatment plants, sewage systems, and heavily exposed structural steel, this coating offers unmatched resistance in even the most corrosive conditions. From industrial concrete surfaces to clarifiers, chain lockers, and void spaces, Coal Tar Epoxy provides heavy-duty protection you can trust.

- Features:**
- **Tough and Flexible:** Durable performance in harsh environments.
 - **Primer-Free Application:** Reduces time and complexity during application.
 - **Bio-Bacterial Resistance:** Protects against microbial degradation.
 - **Superior Corrosion Resistance:** Withstands severely corrosive environments.
 - **Weatherproof Protection:** Long-lasting durability in all conditions.
 - **Versatile Application:** Suitable for steel, concrete, and marine exposures.
 - **Heavy Duty:** Ideal for thick coats applied via heavy-duty airless spray equipment.
 - **Low Water Absorption:** Excellent barrier properties against water ingress.

Technical Properties:	Color / Shades	Black & dark Brown		
	Gloss	Smooth & Glossy		
	Volume Solids	95 + 5 %		
	Mix ratio	3:1 by volume		
	Recommended DFT	100–1000 microns [3.9-39 mils] dry equivalent to 105-1053 microns [4.1-41 mils] wet]		
	Coverage	3.2 m ² /liter at 300 microns DFT (theoretical)		
	Flash Point (Typical)	106°C (223°F)		
	VOC	-		
	Reducer/Thinner	Thinner E1		
	Cleaner	Thinner C1		
	Drying Time	Surface	25°C	
		Temperature		
		Touch	45 to 60 minutes depending on atmospheric temp.	
	Stack Dry	1 to 2 Hours		
	Hard Dry	Overnight		



Polyguard 6612

COAL TAR EPOXY

Cure to Service	7 Days
Pot Life	15 to 20 Minutes

The drying times mentioned are based on a dry film thickness of 300 microns under standard conditions.

Surface Preparation: All surfaces should be clean, dry and free from contamination. The surface should be assessed and treated in accordance with ISO 8504.

Bare Steel:

Cleanliness: Blast cleaning to min. Sa 2 ½ (ISO 85011:2007).

Roughness: Using abrasives suitable to achieve Grade Medium G (50 - 75 µm, Rz scale) (ISO 8503-2).

Other Surfaces:

The coating may be used on other substrates. Please contact TRPL for more information.

Application	Application Method	Thinning	Application Parameters
	Spray	NA	Use a heavy-duty multi-component airless hot spray system with a tip pressure of 200 to 220 bar.
	Brush and Roller	NA	For stripe coating or small areas, it is crucial to achieve the specified dry film thickness and a uniformly coated surface.

For brush application, use nylon or polyester bristles. A 3/8" woven roller cover with a solvent-resistant core should be used for roller application.

Note:

- The material is supplied in two containers as a complete unit. Always mix the entire unit in the proportions provided.
- Stir the base thoroughly for optimal results and homogeneity.
- Mixing 3 parts Comp. A (base) is to be mixed thoroughly with 1 part Hardener, Comp.B (curing agent) through an online static mixer, and ensure the paint mix is homogenous before spray. It should be 100 % ionization of spraying film during application on substrates.

Application Conditions **Substrate Temperature:** Must be at least 10°C and 5°C above the dew point of the air to prevent condensation.

Induction Time: Follow the specified induction time after mixing components to ensure optimal coating adhesion.

Relative Humidity: This should be maintained below 85% during application to achieve desired results.

Environmental Monitoring: Regularly measure temperature and humidity in the application area to ensure compliance.

Ventilation: Ensure adequate ventilation in confined spaces for proper drying and curing.

Curing Period: Protect the coating from exposure to oil, chemicals, or mechanical stress until it has fully cured.



Polyguard 6612

COAL TAR EPOXY

System Cleaning Flush thoroughly the application equipment with TRPL cleaning agent TH -8248 prior and after to application.

Pressure at nozzle: 20 - 22 MPa (200 to 220 bar.)

Nozzle tip sizes: 35 to 43 thau depend on production rate.

Spray angle: 90° - 110°

Filters size and cleaning procedure:

Filters should be cleaned, both in the pump and the spray gun after a certain frequency to avoid coating system chock-up and filters' recommended sizes shall be 80 and 100 mesh to smooth and trouble-free operation.

Paint Transfer Part -A Base arid Part-B Hardener shall be Heat indirectly at 65°C to 75°C as well as 55°C to 65°C respectively before application of paint and passing through filter strainers without fail. The coating system shall be cleaned thoroughly after a stoppage in case of a 6 to 8-hour stay.

Additional Notes It is of vital importance that the nozzle and other parts including the static mixer of the spraying equipment are cleaned properly directly after the work is done due to the short pot life high build liquid coal tar epoxy paint.

- The hoses should be used at high temp and pressure of good quality and no longer than necessary.
- Hose length between mixer and gun shall be less than 1.5 meters.
- Preferably store both paint components at 20 - 25°C. Beware that higher storage temperature will shorten the life of the paint.

For stripe/repair coating, however, a lower paint temperature may be favorable, to get a sufficient pot life.

Storage **Shelf Life:** 12 Months, Sealed Condition

Storage Conditions: Store indoors at 4.5°C [40°F] to 38°C [100°F]

The product must be stored in accordance with national regulations. Keep the containers in a cool and dry place and well-ventilated area with no direct source of heat or light. Containers must be kept tightly closed when not in use.

Safety: Handle with care. Before & during use, observe all safety labels on packaging and paint containers, consult Material Safety Data Sheets, and follow all local or national safety regulations. Avoid inhalation, avoid contact with skin & eyes, and do not swallow. Take precautions against possible risks of fire or explosions as well as protection of the environment. Apply only in well-ventilated areas.

Disclaimer: The information in this document is given to the best of TRPL's knowledge, based on laboratory testing & practical experience. TRPL products are considered semi-finished goods, as such products are often used beyond TRPL's control. TRPL can not guarantee anything but the quality of the product itself. Minor product variations may be implemented to comply with local requirements. TRPL reserves the right to change the given data without further notice. User should always consult TRPL for specific guidance on the general suitability of the product for their needs and specific application practices.